


BELZONA PROTECTS A FLOOR OF A LEADING EUROPEAN COMPANY.

ID: 8303



PROBLEM

The large floor area had cracked as the concrete did not allow for any expansion joints. When the concrete expanded the concrete had cracked in multiple places leaving the client with healthy and safety issues.

APPLICATION SITUATION

The flooring of a large company in the industry of surface coating of metals and plastics in Europe had deteriorated which required a long lasting chemical resistant floor coating.

APPLICATION METHOD

The concrete substrate was abraded to expose the aggregate, the surface was sprayed with Belzona 5811 using airless spraying equipment in accordance with Belzona System Leaflet FPA-3. The expansion joints were filled using Belzona 4521 in accordance with Belzona System Leaflet FPA-6

BELZONA FACTS

The client chose Belzona due to using Belzona products in other small areas of the production facility to resist chemical attack. This flooring opportunity was awarded due to the reliability of the Belzona products in the other areas of this facility.

INDUSTRY

General Industry

LOCATION

Switzerland

APPLICATION DATE

2019

PRODUCTS

Belzona 5811 was selected due to the large floor area and allowing this product to be spray applied whilst also offering chemical resistance incorporating a broadcast of aggregate for a slip resistant finish. Belzona 4521 was used as an Elastomeric sealing system for the expansion joints.

SUBSTRATE

Concrete

PHOTOS

1. Floor Preparation
2. Airless Spraying of Belzona 5811
3. Close up of incorporated aggregate
4. Complete Job

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

