


PAVING SLAB WALKWAY REPAIR WITH BELZONA

ID: 8305



PROBLEM

Removing & replacing the paving slabs would have been a highly disruptive & costly undertaking. A durable & aesthetically pleasing repair solution was required that could be applied to the slabs whilst they remained in place.

APPLICATION SITUATION

Marshall's paving slabs had been installed on a domestic walkway as step treads. These slabs had started to deteriorate through wear, age & weathering. The slabs had lost their original colour & now had a dull appearance. The slabs were then replaced at the expense of the installer but after a further six years the replacements had also deteriorated. A permanent solution was required.

APPLICATION METHOD

The Belzona 4111 Base was colour matched to the original Marshall's paving slabs using the Grey/Sandstone shades & cement pigments. Belzona 4911 TX Conditioner was applied to the areas followed by the mixed Belzona 4111 Magma Quartz.

BELZONA FACTS

By using the Belzona solution there was no need for the removal of the existing paving slabs. These slabs could remain in place whilst being protected by a hard wearing & aesthetically pleasing material.

INDUSTRY

Buildings & Structures

LOCATION

Scotland

APPLICATION DATE

2019 & 2020

PRODUCTS

Belzona 4111 (Magma Quartz)
Belzona 4911 (TX Conditioner)

SUBSTRATE

Stone Paving Slabs

PHOTOS

1. Paving slabs original
2. Wear & weathering of the existing slabs
3. Belzona 4111 colour matched & applied

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

