

BELZONA PROTECTS PHARMACEUTICAL PLANT FLOOR

ID: 8317



PROBLEM

This plant floor and sump area were located outside and the outdoor roof didn't cover the full area, this was causing the concrete to degrade over time. Also, due to process there was occasional chemical spillages onto the concrete and therefore the client wanted the concrete sealing.

APPLICATION SITUATION

Installation of a new positive grip flooring system on an outdoor concrete floor.

APPLICATION METHOD

This application was carried out in accordance with system leaflet FPA-03. The concrete floor was prepared through grinding and cleaned before applying the Belzona 5231 with rollers.

BELZONA FACTS

The whole application was carried out within 2 days without having to disturb the process.

INDUSTRY

Buildings & Structures

LOCATION

Italy

APPLICATION DATE

2017

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Before application
2. Before application
3. Final application
4. Final application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

