


BELZONA 2311 REPAIRS WASTE INCINERATION PLANT CONVEYOR BELT

ID: 8347



PROBLEM

There were a number of tears in the conveyor belts due to the medium that was being transported along the conveyors. If the belts had torn completely the waste would have spread all over the internal of the operation and also the whole plant would have to be shut down to repair.

APPLICATION SITUATION

A conveyor belt had torn during operation within a waste incineration plant. Conveyor belts transport biomass from the waste heap to shredders or transfer stations.

APPLICATION METHOD

The application of the Belzona 2311 is very fast and effective due to its fast curing nature. The product was applied in accordance with Belzona System Leaflet SHM-1.

BELZONA FACTS

The local Swiss distributor were contacted due to the nature of the quick repair and the Belzona 2311 being able to fix the belt and back in service within 1 hour of full mechanical loading.

INDUSTRY

Water / Wastewater

LOCATION

Switzerland

APPLICATION DATE

June, 2019

PRODUCTS

Belzona 2311 and Belzona 2911

SUBSTRATE

Rubber

PHOTOS

Picture 1 - Conveyor System

Picture 2 - Conveyor Belt Tear

Picture 3 - Belzona 2311

Picture 4 - Application Complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

