

BELZONA REPAIRS, PROTECTS & IMPROVES PUMP TURBINES IN THE PETROCHEMICAL INDUSTRY

ID: 8349



PROBLEM

Water pump impellers were suffering extensively from cavitation and erosion.

APPLICATION SITUATION

Water pump on a petrochemical site.

APPLICATION METHOD

The application was carried out, in accordance with Belzona System Leaflet CEP-01 and CEP-10, where the damaged areas were rebuilt using Belzona 1111 and then coated with Belzona 1341 to predominantly solve the clients cavitation problem.

BELZONA FACTS

An alternative repair method had previously been used but failed due to poor surface preparation standards. The Belzona Distributor applied the product on behalf of the client, providing therefore, not only the product but also the technical and application support the customer required.

INDUSTRY

Chemical & Petrochemical

LOCATION

Mohammedia, Morocco

APPLICATION DATE

July 2020

PRODUCTS

Belzona 1111 (Super Metal) and Belzona 1341 (Supermetalgilde)

SUBSTRATE

Bronze

PHOTOS

- 1). Damage sustained on the impeller
- 2). Impeller once taken back to the substrate
- 3). Impeller after rebuilding
- 4). Finished product

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

