



WELDING SEAMS PROTECTION

ID: 8360



PROBLEM

Corrosion on welds. A protective coating was the only option to prevent corrosion.

APPLICATION SITUATION

Tank for gasoline storing shows corrosion on the welding seams.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC 3

BELZONA FACTS

Customer needed quick and quality repair. All welding seams were coated by Belzona 1341. Coating was done in 2016. After 4 years no damage was appeared.

INDUSTRY

Chemical & Petrochemical

LOCATION

Petrochemical company, Slovakia

APPLICATION DATE

October 2021

PRODUCTS

Belzona 1341

SUBSTRATE

Carbon steel

PHOTOS

1. Corrosion on the welding seams
2. Welding seams was coated by Belzona 1341
3. Welding seams was coated by Belzona 1341
4. After 4 years no damage was appeared.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

