

BELZONA SEALS A WIND TURBINE TOWER BASE

ID: 8375



PROBLEM

The contractor sought guidance as there were several areas showing signs of metal corrosion and minor cracks to the concrete areas of two bases. A repair and protect solution was required to ensure the asset life could be fully extended a further ten years.

APPLICATION SITUATION

The set of ten wind turbines is situated rurally and passing into the second ten years of service. The contractor responsible to maintain the asset life identified some areas of failure to the wind turbine base.

APPLICATION METHOD

The application was carried out in accordance with a variance of GSS-03

BELZONA FACTS

The contractor selected the turnkey services of Belzona in consideration of the vast experience and application techniques. Other optional alternatives did not meet the criteria. Upon completion we were informed that the remaining eight bases would be undertaken during 2021.

INDUSTRY

Power

LOCATION

South Wales UK

APPLICATION DATE

July 2020

PRODUCTS

Belzona 3131 WG Membrane
Belzona 3921 & 3931 Conditioners
Belzona 9361 Reinforcing Sheet

SUBSTRATE

Steel & Concrete C32/C40

PHOTOS

- 1 - Visual preparation
- 2 - Surface preparation, concrete, steel and conditioners
- 3 - Two coat system including reinforcing sheet
- 4 - Fully completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

