

PENSTOCK OUTER SURFACE COATED WITH BELZONA

ID: 8383



PROBLEM

The outer surface of the penstock was constantly exposed to moisture. Previously painting swelled in a short time.

APPLICATION SITUATION

The customer was disturbed by the bad appearance of the swelling of the paint on Penstocks. The material to be selected should be suitable for the moisture during the application.

APPLICATION METHOD

The application was carried out in accordance with belzona System Leaflet TCC-03.

BELZONA FACTS

After a very good surface preparation, although the surface was moist during application, it was a successful application because the selected Belzona product was suitable for this.

INDUSTRY

Power

LOCATION

Hydro Power Plant, TURKEY

APPLICATION DATE

September 2020

PRODUCTS

Belzona 5831 (ST Barrier)

SUBSTRATE

Steel

PHOTOS

- 1- Before surface preparation, painted surface
- 2- After grit blasting
- 3- When applying the second coat of Belzona 5831
- 4- End of application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

