

BELZONA REPAIR AND PROTECTS SCRUBBER ELBOW PIPE

ID: 8388



PROBLEM

Internal surfaces of scrubber pipes are exposed to high corrosion and cavitation due to corrosive effects of the Scrubber Exhaust Discharge Water.

APPLICATION SITUATION

On board scrubber elbow pipes of Ro-Ro vessel

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-03 and CEP-05. Scrubber pipe surfaces have been prepared on board by the shipyard. All surfaces were thoroughly cleaned. Then the damaged surfaces and pittings were repaired with Belzona 1511 Super HT-Metal before coating with Belzona 1391T to provide overall erosion-corrosion and chemical protection.

BELZONA FACTS

It is substantially more cost-effective to repair and protect with Belzona versus replacement. In short time scrubber transition pipes were repaired and protected against severe corrosive conditions of Scrubber Water. The application has been completed in one day without any hot works. Pipes are now protected against future erosion-corrosion damages.

INDUSTRY

Marine

LOCATION

SHIPYARD, TURKEY

APPLICATION DATE

September 2020

PRODUCTS

Belzona 1511 Super HT-Metal and Belzona 1391T

SUBSTRATE

Steel

PHOTOS

1. Scrubber Elbow Pipe
2. After first coat of Belzona 1391T
3. After second coat of Belzona 1391T
4. Sponge test on coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

