

BELZONA CHOCKING COMPOUND STABILIZES A LATHE

ID: 8393



PROBLEM

Lathe required a solution to withstand compressive load of machinery and reduce vibrations.

APPLICATION SITUATION

Installed lathe at a machine building manufacturer which required a solid foundation.

APPLICATION METHOD

Belzona System Leaflet GSS-13 was used to set up and apply Belzona 7111 to precisely align the equipment.

BELZONA FACTS

The Belzona solution secured the equipment for the long-term. Normally the machine would be bolted to the floor, which doesn't prevent corrosion or damage to the baseplate due to vibration.

INDUSTRY

Steel & Metal Processing

LOCATION

Malacky, Slovakia

APPLICATION DATE

2020

PRODUCTS

Belzona 7111 (Industrial Grade)

SUBSTRATE

Concrete, steel

PHOTOS

1. Installed lathe required a solid foundation
2. Temporary wood dam prepared
3. Pouring Belzona 7111
4. Final Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

