

BELZONA 1593 SPECIAL INTERNAL COATING

ID: 8395



PROBLEM

Chemical attack (corrosion) was only one problem, another problem was that coating area was not easy available.

APPLICATION SITUATION

Customer needed to protect internal tube sheet of the air condenser. We have offered him product Belzona 1593, which could be used for hydrocarbons in 150°C.

APPLICATION METHOD

We needed to use special tools for blasting through the threaded holes with diameter 18 mm. Also we had to protect that thread. After blasting and cleaning, a tube sheet was coated with product Belzona 1593 in 2 layers. The application was performed in accordance with a modified Belzona system leaflet HEX-03.

BELZONA FACTS

Customer has no idea how to make this protection without any fail. They were very pleased with the protection of the equipment and on completion of the application commented on the professionalism of the application team. Our solution saved the customer a huge amount of money.

INDUSTRY

Oil & Gas

LOCATION

Bratislava, Slovakia

APPLICATION DATE

2020

PRODUCTS

Belzona 1593

SUBSTRATE

Steel

PHOTOS

1. Customer needed to protect internal tube sheet
2. We needed to use special tools for blasting
3. Tube sheet was coated with product Belzona 1593
4. Ready to work

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.