

BELZONA KEEPS FISHING FOR 20 YEARS.

ID: 8427



PROBLEM

Now in 2020, some 20 years after the original application, some localized areas required attention and re-laying of Belzona 4111.

APPLICATION SITUATION

The area adjacent to the stern ramp of the trawling vessel is a constant trafficable area for the crew as well as weighted nets full of the catch of the day being dragged across the deck. Back In 2000 the engineer in charge applied one of the Belzona 4000 products to the deck area for non slip and durability.

APPLICATION METHOD

The localized areas were mechanically abraded and the Belzona 4111 was troweled into the areas to be patched.

BELZONA FACTS

The same engineer applied both Belzona products some 20 years apart - it was very evident that the original Belzona was extremely durable and robust making the decision to carry out the patch repairs with Belzona a very easy one.

INDUSTRY

Marine

LOCATION

Perth, Western Australia

APPLICATION DATE

2000 and 2020

PRODUCTS

Belzona 4911 (Magma TX conditioner)
Belzona 4111 (Magma Quartz)

SUBSTRATE

Steel

PHOTOS

1. Fishing Trawlers
2. Stern ramp deck prior to repair
3. Close up of original 20 year old Belzona 4000 product
4. New repairs complete.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.