

BELZONA REPAIRS TO ROOFTOP EXHAUST DUCTING

ID: 843



PROBLEM

Joints were leaking allowing escape of unpleasant gases into the neighbourhood leading to many complaints.

APPLICATION SITUATION

Rooftop exhaust ductwork

APPLICATION METHOD

Application carried out using a modified Belzona System VPF-11a

BELZONA FACTS

Years of successful repairs, some of them very difficult, gave client the confidence to proceed with Belzona repairs.

INDUSTRY

General Industry

LOCATION

Pet food manufacturer, MO

APPLICATION DATE

April 2007

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Galvanized metal

PHOTOS

1. First duct joint
2. Close up of first joint repair
3. Second joint repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

