

BELZONA PROTECTS NEW BUTYL GLYCOL ESTERS TANKS

ID: 8446



PROBLEM

Internal corrosion of tanks damaged due to corrosion and failure of previous coating.

APPLICATION SITUATION

Butyl glycol esters tanks needed a protective coating.

APPLICATION METHOD

Application was carried out in accordance with Belzona system Leaflet TCC-5.

BELZONA FACTS

The client had used a cheap coating in containment area first and after it failed decided to spend a little more money to make it last a long time. Belzona 4311 was applied into the internal lining of the tank and is still in good condition.

INDUSTRY

Chemical & Petrochemical

LOCATION

Lubin, Poland

APPLICATION DATE

June 2020

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Steel

PHOTOS

1. Asset Location
2. Butyl glycol esters tanks
3. Previous coating corrosion protection damage.
4. Inspection after one year

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

