

BELZONA HELPS PROTECT OFFSHORE PLATFORM LEGS AT A WATERLINE

ID: 8447



PROBLEM

Corrosion of platform legs in the splash zones.

APPLICATION SITUATION

Original corrosion protection damaged on platform legs.

APPLICATION METHOD

Application was carried out using a modified version of Belzona Know-How System Leaflet SOS-21. After wet abrasive blasting the Belzona 5831 was applied to the corroded areas above the waterline.

BELZONA FACTS

The surface tolerant properties of Belzona 5831 made it the ideal solution for these difficult access conditions. The product provides excellent adhesion to surfaces both in the splash zone and underwater.

INDUSTRY

Oil & Gas

LOCATION

Baltic Sea

APPLICATION DATE

September 2020

PRODUCTS

Belzona 5831 (ST Barrier)

SUBSTRATE

Steel

PHOTOS

1. Corroded platform legs
2. Surface preparation
3. Belzona 5831 in use.
4. Platform

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

