



# BELZONA FURNITURE REPAIR

ID: 8482



## PROBLEM

The user needed to use this wardrobe immediately, without any dismantling, with repair for a long time.

## APPLICATION SITUATION

After long time using was the wardrobe door hinge ripped out

## APPLICATION METHOD

Application was carried out using adapted Know-How System Leaflet ENC-2.

## BELZONA FACTS

User knows Belzona products from industry using. He needed quick, good and long- standing repair. Belzona 1212 was his genuine solution.

## INDUSTRY

Buildings & Structures

## LOCATION

Slovakia

## APPLICATION DATE

2019

## PRODUCTS

Belzona 1212

## SUBSTRATE

Chipboard

## PHOTOS

1. Ripped out door hinge
2. Belzona 1212 application
3. Installation in short time
4. Ready to use

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © 1952-2026 Belzona International Limited.

  
**BELZONA®**