

BUSH HOUSING BONDED IN PLACE WITH BELZONA

ID: 8559



PROBLEM

Welding was very undesirable due to the risk of heat distortion. It also would not have addressed the issue of galvanic corrosion between the two dissimilar metal parts.

APPLICATION SITUATION

A bush housing had become oversize due to wear & corrosion. The bush was spinning whilst the machinery was in operation, this was causing further wear.

APPLICATION METHOD

The housing & bush were prepared using an angle grinder. Belzona 1111 (Supermetal) was then applied to both parts. The bush was then inserted & aligned.

BELZONA FACTS

By utilising the Belzona repair the machinery was running again the next day with no risk of heat distortion during the repair process.

INDUSTRY

LOCATION

Scotland

APPLICATION DATE

July 2021

PRODUCTS

Belzona 1111 (Supermetal)

SUBSTRATE

Mild steel

PHOTOS

- 1 - Conveyor system
- 2 - Surface preparation on the housing
- 3 - Bushing to be bonded in place
- 4 - Belzona 1111 Supermetal applied & bushing bonded

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

