

REPAIR OF DRINKING WATER TANK WITH BELZONA 5811DW2

ID: 8560



PROBLEM

The concrete walls of the water tank had corroded over time leading to deterioration of the substrate subsequently leading to a poorer quality water quality.

APPLICATION SITUATION

Renovation of a Water tank on site using a Belzona Drinking Water approved coating.

APPLICATION METHOD

The Belzona products were applied in accordance with the Belzona System Leaflet TCC_5.

BELZONA FACTS

Belzona 5811DW2 is a WRAS approved coating for Potable Water, spray applied allowing for a quick and easy return to service.

INDUSTRY

Food & Drink

LOCATION

Poland

APPLICATION DATE

July 2021

PRODUCTS

Belzona 5811DW2
Belzona 4111
Belzona 4911

SUBSTRATE

Concrete

PHOTOS

Image 1: Inside of the Water Tank

Image 2: Re-Build of the Concrete using Belzona 4111

Image 3: Spraying Belzona 5811DW2

Image 4: Completed Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

