

BELZONA RE-SURFACES WATER PARK FLOORS

ID: 858



PROBLEM

Painted floors in bathrooms and outside surfaces were wearing out on a yearly basis and the city was looking for a long term solution.

APPLICATION SITUATION

Bathroom floors and outside surfaces in a water park.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet FPA-8.

BELZONA FACTS

Belzona product was found to provide a long term solution compared to original paint system which required annual replacement.

INDUSTRY

General Industry

LOCATION

Water Park - Oklahoma

APPLICATION DATE

May 2007

PRODUCTS

Belzona 5111 (Ceramic Cladding) Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. Bathroom floors before application.
2. Bathroom floors after Belzona 5111 was applied.
3. Outside surfaces before application.
4. Outside surfaces after Belzona 5111 application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

