

BELZONA SEALS UNSANITARY LEAKING FLOOR DRAIN IN FOOD PLANT

ID: 860



PROBLEM

Leak around drain allowed waste product into the sanitary production packaging floor below.

APPLICATION SITUATION

Waste drain on 2nd floor above production packing area.

APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

Only a small amount of product used to solve a health hazard and to meet American Baking Association standard of cleanliness. This client has a long history of successful Belzona applications.

INDUSTRY

General Industry

LOCATION

Pet food manufacturer, O'Fallon, MO

APPLICATION DATE

June 2007

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Unsanitary, leaking drain
2. Surface prepared
3. Belzona 4111 installed
4. Drain cover installed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

