



INDUSTRIAL FLOOR COATED WITH BELZONA

ID: 8621



PROBLEM

Degradation of the floor surface could lead to the occurrence of potentially dangerous events, i.e. overturning the trolley, tripping within the production hall.

APPLICATION SITUATION

Maintaining the required hygiene and cleanliness of the production hall. Unevenness of the floor surface and damage to the pedestals arose as a result of intensive vehicular traffic of internal transport.

APPLICATION METHOD

Replenishment of cavities, repair of the floor surface, making a new smooth washable surface. Low-cost technology compared to traditional methods, applied in accordance with Belzona system leaflet FPA-3.

BELZONA FACTS

The client can be assured that when washing with chemicals they will not have to worry about the degradation of the coating or concrete.

INDUSTRY

Buildings & Structures

LOCATION

Poland

APPLICATION DATE

August 2021

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

Image 1 - Damaged floor to be repaired with Belzona 4111

Image 2 - Vacuuming up any loose debris and dust.

Image 3 - Roller Brush Application of Belzona 5231

Image 4 - Completed Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.