

BELZONA PROTECTS CLARIFIER TRACK

ID: 8622



PROBLEM

The damage on the track on the clarifier needed to be rebuilt to a smooth surface in order to allow the operation of the 'crane' unit.

APPLICATION SITUATION

The track on an effluent clarifier had become damaged over time, so a solution was needed to rectify this.

APPLICATION METHOD

Any loose material was removed and shuttering installed to the required height. The substrate was conditioned with Belzona 4911 and rebuilt with Belzona 4111.

BELZONA FACTS

The works to repair the entirety of the 80m tank circumference were completed in just 5 days.

INDUSTRY

Water / Wastewater

LOCATION

Italy

APPLICATION DATE

2021

PRODUCTS

Belzona 4911

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Removal of spooled and damaged concrete
2. Removal of spooled and damaged concrete
3. Conditioning of the substrate
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

