




BELZONA PREVENTS WATER DAMAGE ON A HOSPITAL ROOF

ID: 8629



PROBLEM

Rainwater was penetrating into the building

APPLICATION SITUATION

Rainwater was filling the gutters and entering behind the flashing into the building.

APPLICATION METHOD

The application was cleaned of any loose material and degreased. The first layer of Belzona 3121 (MR7) was applied and the reinforcement sheet stipled in. Then the 2nd coat was applied and left to cure.

BELZONA FACTS

Belzona offered an effective method of stopping any further leaks without the need to replace any of the guttering or flashing.

INDUSTRY

Buildings & Structures

LOCATION

Alabama

APPLICATION DATE

2021

PRODUCTS

Belzona 3121 (MR7)

SUBSTRATE

Metallic Joints

PHOTOS

1. Original condition of the guttering
2. Application in progress
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

