

BELZONA RESEALS AROUND ROOFTOP A/C UNITS

ID: 863



PROBLEM

Over zealous painter overcoated Belzona repair with an aluminum paint that caused the Membrane to crack leading to roof leaks

APPLICATION SITUATION

This unit was successfully sealed with Belzona® 3111 over 10 years ago.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-8

BELZONA FACTS

Previous success of the Belzona® 3111 and reluctant admission of mistakenly applying aluminized paint over the Belzona® 3111 coating lead to re-installation of the Belzona. Reroofing was the alternative to repairing a small portion of the 25,000 sq ft roof.

INDUSTRY

Pulp & Paper

LOCATION

Chic Lumber Co, OFallon, MO

APPLICATION DATE

July 2007

PRODUCTS

Belzona® 3111 (Flexible Membrane)

SUBSTRATE

Tar, Aluminum paint and Belzona® 3111

PHOTOS

1. Start of the application
2. Sheet being incorporated in Belzona 3111 coating
3. Application continuing
4. All sides waterproofed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

