

BELZONA PROTECTS PUMPS FOR WATER TREATMENT PLANT

ID: 8631



PROBLEM

Pump linings suffer from erosion and corrosion over time due to exposure to the process stream. A lining resistant to erosion was required

APPLICATION SITUATION

Water treatment pumps required protection

APPLICATION METHOD

Belzona 1331 was applied to the grit-blasted internals of the pumps

BELZONA FACTS

This was the second set of pumps to be protected by Belzona as they had no problems with their first set upon inspection, a few years after the initial installation.

INDUSTRY

Water / Wastewater

LOCATION

US

APPLICATION DATE

2021

PRODUCTS

Belzona 1331

SUBSTRATE

Steel

PHOTOS

1-3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

