

SUMP REPAIR WITH BELZONA AT YEAST PLANT

ID: 866



PROBLEM

After years of running 24 hours a day, 7 days a week the sump had erosion and corrosion from chemical attack at the water level.

APPLICATION SITUATION

Sump receiving waste water from the plant.

APPLICATION METHOD

This application was carried out in accordance with Belzona Know-How System Leaflet FPA-10.

BELZONA FACTS

The Belzona® 4111 will hold up to the the chemical attack providing long life to the sump. The Belzona solution provided the customer the ability to be back on-line in under 24 hours.

INDUSTRY

General Industry

LOCATION

Yeast Producer, Memphis, TN

APPLICATION DATE

March 2007

PRODUCTS

Belzona 4111 (Magma Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Sump prior to repair
2. Sump under repair
3. Sump after repair
4. Sump after repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

