

BELZONA REPAIRS BIODIESEL COLUMN

ID: 867



PROBLEM

Due to stress on a flange there was a crack at the weld causing Biodiesel to leak. This was 130 feet above the ground.

APPLICATION SITUATION

Biodiesel Column

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-3 & 6.

BELZONA FACTS

The Belzona solution offered the customer quick turn-around, without the expense of having to empty the column which they would have had to do if welding.

INDUSTRY

Chemical & Petrochemical

LOCATION

Biodiesel Producer, Memphis, TN

APPLICATION DATE

November 2006

PRODUCTS

Belzona 4301 (Magma CR1 Hi-Build)

SUBSTRATE

Stainless Steel

PHOTOS

1. The column to be repaired
2. Column under repair
3. Repaired area on column
4. Repaired area close-up

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

