

BELZONA PROTECTS TANK FROM EXTERNAL CORROSION

ID: 8684



PROBLEM

External corrosion and chemical attack of the existing coating

APPLICATION SITUATION

A tank required protection from external corrosion at a food production facility.

APPLICATION METHOD

The surface was grit blasted and Belzona 5811 applied per IFU and system leaflet TCC-03

BELZONA FACTS

Belzona 5811 offers cost-effective protection from environmental and chemical attack, which will help extend the lifespan of this piece of equipment

INDUSTRY

Food & Drink

LOCATION

South Africa

APPLICATION DATE

2021

PRODUCTS

Belzona 5811 (Immersion grade)

SUBSTRATE

Steel

PHOTOS

1. Tank prior to surface preparation 2. Tank during surface preparation 3. Tank post surface preparation 4. Completed Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

