


# BELZONA REBUILDS & PROTECTS BEET WASHERS

ID: 8700



## PROBLEM

Due to the demanding nature of the sugar beet washers operation - humidity, abrasion and erosion - leading to accelerated rates of corrosion and wear resulting in through wall defects due to repeated abrasion and erosion from the sugar beet during operation.

## APPLICATION SITUATION

Sugar beet washers used to clean sugar beets in order to calculate average cost of clean sugar beet vs. dirty sugar beet were worn and damaged.

## APPLICATION METHOD

The wash bowl and top lid, were grit blasted prior to being rebuilt to their original profile using Belzona 1111. This was followed by the application of Belzona 1812 which has ceramic fillers inside to reduce and combat the abrasive wear, providing resistance to fine particle abrasion in particular. The bowl and lid were then coated using Belzona 1321 to provide a smoother surface on top of the sacrificial lining. The application was carried out in accordance with Belzona System Leaflet GSS-5 & GSS-9.

## BELZONA FACTS

The customer was so happy with phase 1 of the project that he commissioned phase 2 which took place in 2018.

## INDUSTRY

Sugar

## LOCATION

Czech Republic

## APPLICATION DATE

January 2016 (Phase 1)

## PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1812 (Ceramic Carbide FP)

Belzona 1321 (Ceramic S-Metal)

## SUBSTRATE

Cast Iron / Steel

## PHOTOS

- 1). Deteriated Beet Washers in Situ,
- 2). Partial Belzona 1812 coated Wash Bowl,
- 3). Partial Belzona 1812 coated Lid,
- 4). Top Coated Lid using Belzona 1321

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

