

# BELZONA PROTECTS HOT WATER TANKS

ID: 871



## PROBLEM

Severe internal corrosion

## APPLICATION SITUATION

Hot water generation tanks within the Powerhouse.

## APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

## BELZONA FACTS

This application saved over \$60,000 against cost of replacement.

## INDUSTRY

Heating, Ventilation & Air Conditioning

## LOCATION

State Correctional Facility, Missouri

## APPLICATION DATE

February 2007

## PRODUCTS

Belzona 5811 (Immersion Grade)  
Belzona 1111 (Super Metal)

## SUBSTRATE

Steel

## PHOTOS

1. The tank inside the Powerhouse
2. View of the internal corrosion
3. Contractor applying 2nd coat of Belzona 5811
4. Technical Consultant inside the finished tank 2 days later

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

