

BELZONA REPAIR TO POWER PLANT COAL BELT

ID: 874



PROBLEM

Belt developed a large burn hole. This rendered the belt unusable until fixed.

APPLICATION SITUATION

One of a series of large belts used to bring coal from the coal yard to the plant.

APPLICATION METHOD

Belt was repaired according to Belzona System Laflet SHM-1

BELZONA FACTS

The company that usually repairs their belts takes a long time to respond to service requests and are very expensive. They needed the repair completed quickly. The belt was repaired in a matter of hours and the plant now uses Belzona for all belt repairs.

INDUSTRY

Power

LOCATION

Power Station, Missouri

APPLICATION DATE

2007

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Hole in the belt being prepared
2. Preparation completed
3. Completed application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

