

TANK BASE SEALING WITH BELZONA SOLUTION

ID: 878



PROBLEM

Moisture was seeping through the concrete tank pad and collecting under the tank. Plant officials feared that the tank bottom would be compromised by subsequent corrosion.

APPLICATION SITUATION

Large oil tank

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet GSS-3

BELZONA FACTS

Other products had failed to seal the chime angle. Plant engineers were needing a reliable product that would adhere to both substrates. Belzona was chosen for its ease of application and excellent reputation. The application was completed quickly and effectively.

INDUSTRY

Power

LOCATION

Coal Fired Power Plant, Missouri

APPLICATION DATE

2007

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Carbon Steel/ Concrete

PHOTOS

1. Chime angle before application
2. Application underway
3. View of tank size
4. Completed Application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

