

# BELZONA PROTECTS INLET SPOOLS OF AN ALSTOM SEAWATER PUMP

ID: 8787



## PROBLEM

The inlet spool of an Alstom sea pump was cracked (1500mm along the length of the spool) on the outside and suffered corrosion due to sea water, therefore needing to be repaired and protected against future wear along with other parts of the pump.

## APPLICATION SITUATION

Inlet spool of a sea pump at a Thermal Power Plant.

## APPLICATION METHOD

The crack in the inlet spool was terminated and V-ed to prevent future crack propagation, and was then filled in using Belzona 1311 and Belzona 9341 reinforcement sheet from both inside and outside of spool. The whole spool was then overcoated using Belzona 1321. The application was carried out in accordance with Belzona System Leaflet CEP-06 & PDP-05.

## BELZONA FACTS

The turbine is still in service today and is holding up well to its operational environment - the customer therefore approves of the quality of the repairs and durability of the Belzona products used.

## INDUSTRY

Power

## LOCATION

Jorf Lasfar, Morocco

## APPLICATION DATE

November 2020

## PRODUCTS

Belzona 1311 (Ceramic R-Metal) Belzona 9341 (Reinforcement Sheet) Belzona 1321 (Ceramic S-Metal)

## SUBSTRATE

Cast Iron

## PHOTOS

1). Original condition of the Inlet Spool. 2). Surface preparation, termination and V-ing out of the 1500mm crack. 3). Reloading of the inlet spool crack and partial coating application. 4). Completed application overcoated with Belzona 1321.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

