

BELZONA BRINGS NEW LIFE TO AN ALSTOM SEA PUMP TURBINE

ID: 8788



PROBLEM

The leading edges of the vanes were severely damaged due to erosion and corrosion, along with the bearing housing of the turbine.

APPLICATION SITUATION

Alstom sea pump turbine at a Thermal Power Plant.

APPLICATION METHOD

The leading edges of the vanes were rebuilt using Belzona 1311 and the turbine was then rebalanced to ensure optimum operating efficiency without causing residual wear to any auxiliary equipment. These were then coated using Belzona 1321 to provide erosion-corrosion protection. The bearing was also repaired to its original profile to ensure a perfect fit with the turbine shaft. The application was carried out in accordance with Belzona System Leaflet PDP-03 & PDP-05.

BELZONA FACTS

The turbine is still in service today and is holding up well to its operational environment - the customer therefore approves of the quality of the repairs and durability of the Belzona products used.

INDUSTRY

Power

LOCATION

Jorf Lasfar, Morocco

APPLICATION DATE

November 2020

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Cast Iron

PHOTOS

- 1). Original damaged state of the turbine.
- 2). Rebuilding of the leading edge on the vanes.
- 3). Rebalancing of the Turbine.
- 4). Completed application of the Turbine.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

