

EXPANSION JOINT AT HOSPITAL SEALED WITH BELZONA

ID: 879



PROBLEM

Expansion joints in the hospital had become a tripping hazard

APPLICATION SITUATION

Expansion joints in corridor in need of repair

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-5 and -6.

BELZONA FACTS

The hospital needed a fast-curing and reliable method for repairing expansion joints that were creating trip hazards for patients.

INDUSTRY

Buildings & Structures

LOCATION

Hospital, Missouri

APPLICATION DATE

2007

PRODUCTS

Belzona 4111 (Magma Quartz) Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. View of joint with kick plate removed
2. Application of Belzona 4111
3. Application of Belzona 2221
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

