


BELZONA REPAIRS SCHOOLS CHILLER

ID: 880



PROBLEM

Years of service had caused extensive corrosion on the chiller tube sheet face.

APPLICATION SITUATION

Corroded chiller face

APPLICATION METHOD

Application was completed in accordance with Belzona System Leaflet HEX-1.

BELZONA FACTS

School officials were aware of Belzonas reputation for quality and reliability.

INDUSTRY

Buildings & Structures

LOCATION

Elementary School, St. Louis, Missouri

APPLICATION DATE

2007

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Corroded tube sheet face
2. Application in progress
3. Completed application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.