


PIPE REPAIR AT A PUMP STATION

ID: 8800



PROBLEM

Heavy corrosion of the internal of the pipes needed repairing to ensure protection of dyke.

APPLICATION SITUATION

A pipe at a pump station for the dyke protection had heavily corroded.

APPLICATION METHOD

The heavy corroded areas were filled and smoothed with Belzona 1111. Belzona 5811 was used to coat the internal and external of the pipe for further corrosion protection.

The application was carried out in accordance with Belzona System Lealeaft VPF-03

BELZONA FACTS

Saved the client replacing the pipe, a relatively quick procedure to repair and coat with Belzona and return back to service.

INDUSTRY

Water / Wastewater

LOCATION

Northern Germany

APPLICATION DATE

2022

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

Image 1: First Layer of Belzona 5811

Image 2: Second Layer of Belzona 5811

Image 3: Internal Application Complete

Image 4: External Application Complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.