

BELZONA REPAIRS AND PROTECTS MACHINE TOOL COOLANT TANK

ID: 884



PROBLEM

The cutting fluid is water based. The tanks rust because the cutting fluid and the cuttings sit on the bottom of the tank. The tanks leak and cause a big mess and safety hazard.

APPLICATION SITUATION

Coolant tanks containing cutting fluid.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

BELZONA FACTS

Successful long term results provide the machinist with a safe worry free work environment.

INDUSTRY

General Industry

LOCATION

Aerospace Component Manufacturer, KS

APPLICATION DATE

February 2007

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Mild Steel

PHOTOS

1. Typical rust holes
2. Blast cleaned tank
3. Totally sealed tank

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

