

BELZONA COATED SHIP SCRUBBER PIPES REVISITED AFTER TWO YEARS IN SERVICE

ID: 8845



PROBLEM

The corrosive and harsh environment of Exhaust Scrubber line fluid caused damage on internal steel pipe surfaces.

APPLICATION SITUATION

Pipes part of the exhaust scrubber line required protection

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet VPF-02 and TCC-05. The surface was prepared and cleaned. Two layers of Belzona 1391T were applied to coat the internal surface of the steel pipe for protection against further corrosion and cavitation damage. After completion of the coating application, post cure has been applied according to the IFU.

BELZONA FACTS

In the corrosive environment of exhaust scrubber lines, Belzona coatings offer protection against corrosion/erosion. The danger of damage and perforation on steel transition pipes was eliminated.

INDUSTRY

Marine

LOCATION

RO – RO SHIP, TURKEY

APPLICATION DATE

August, 2020

PRODUCTS

Belzona 1391T

SUBSTRATE

Steel

PHOTOS

1. Scrubber pipe without any protective coating
2. After applied first coat of Belzona 1391T
3. After applied second coat of Belzona 1391T
4. Checked the condition of the pipes after 2 years of service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

