

BELZONA SUPER WRAP II ON HIGH PRESSURE PIPE OFFSHORE

ID: 8878



PROBLEM

The pipe is a very important part of oil & gas operations for this customer. The application area was difficult to access. External corrosion created thinning of the wall thickness on the pipe causing a solution to be found to protect this pipe.

APPLICATION SITUATION

An 8in diameter liquid hydrocarbon line of a major Oil & Gas Owner on an offshore platform in the Gulf of Mexico experienced external corrosion. UTS was performed to determine the wall thickness of the pipe. The MAWP of the line is 5000psi. The application area was reached via Rope Access. SuperWrap II was chosen as a preventative measure to protect the pipe. Replacement costs are not feasible at this time and a shut in would require a major loss in cash flow.

APPLICATION METHOD

1. Power tool prep via MBX Bristle Blaster to bare metal (SSPC-SP11). Wipe the surface clean with Belzona 9111 and let dry.
2. Belzona 1161 was applied to the thin wall areas.
3. Belzona SuperWrap II system was applied per the design at 3 wraps / 18in axial extent. Belzona 9382 was used to consolidate and allow to cure.

BELZONA FACTS

Products are stocked offshore on platforms year round to allow for quick repairs that are ASME PCC 2 certified. This helps to address urgent repairs quickly, eliminate shut ins and save money for the customer.

INDUSTRY

Oil & Gas

LOCATION

Gulf of Mexico

APPLICATION DATE

October 2022

PRODUCTS

Belzona 9111 Cleaner/Degreaser
Belzona 1161 Super UW Metal
Belzona 1982 Resin
Belzona 9381 84mm
Belzona 9382 Red Release Film
Belzona mixing tools

SUBSTRATE

Carbon steel

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

