


BELZONA SEALS POROUS TANK WELDS

ID: 888



PROBLEM

Porous welds in stainless steel tank. Herbicide is expensive and very slippery. Not only was leaking tank an environmental hazard but a general safety hazard as well.

APPLICATION SITUATION

Stainless steel herbicide tank

APPLICATION METHOD

Application carried out in accordance with Belzona System Leaflet TCC-1. The tank was drained and rinsed. A stainless steel tank cleaner was used to clean the surface.

After preparing the surface,

Two coats of Belzona® 4301 were applied to the weld seams.

BELZONA FACTS

Belzona sealed the leaking tanks helping the owner avoid fines and lawsuits.

Belzona® 4301 is resistant to a wide variety of chemical and was well suited for this repair.

INDUSTRY

General Industry

LOCATION

Herbicide Manufacturer- Bushton, Kansas, USA

APPLICATION DATE

July 2007

PRODUCTS

Belzona 4301 (Magma CR1 Hi-Build)

SUBSTRATE

Stainless Steel

PHOTOS

1. Tank interior before application
2. Tank seams coated with Belzona 4301

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

