


PROTECTION OF THE DISCHARGE PIPE AREA ON SHIP

ID: 8880



PROBLEM

The original glass flake coat had broken after a few years in service. This leaves the ship unprotected and vulnerable to corrosion.

APPLICATION SITUATION

Protection of the surface of the discharge pipe DN600 and the surrounding shell plate of the hull

APPLICATION METHOD

The area was grit blasted, roughness was measured and the salt contamination determined (result ok)
Two coats of 1391T were applied

BELZONA FACTS

By using Belzona 1391T, we secure the ship against corrosion of the hull in a critical location.
The customer will not have to worry about it for many years to come.

INDUSTRY

Marine

LOCATION

Port of Odense (Lindoe ship yard)

APPLICATION DATE

26-10-2022

PRODUCTS

Belzona 1391T

SUBSTRATE

Carbon steel

PHOTOS

1. initial condition of ship
2. initial condition of ship
3. during application
4. application complete

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

