

EXTERNAL CORROSION PROTECTION FOR VALVE PARTS

ID: 8882



PROBLEM

Due to onsite restrictions only manual preparation was permitted in the area. The geometry of the parts is quite complex & challenging to coat with traditional paint systems

APPLICATION SITUATION

Several exposed parts on valves were in need of corrosion protection.

APPLICATION METHOD

The exposed steel was first prepared to a ST-2 standard. Belzona 8411 was then applied followed by two coats of Belzona 3412

BELZONA FACTS

By using the Belzona system it was possible to accurately coat the parts whilst minimizing any hazards to the site

INDUSTRY

Chemical & Petrochemical

LOCATION

Scotland

APPLICATION DATE

July 2022

PRODUCTS

Belzona 8411

Belzona 3412

SUBSTRATE

Carbon steel

PHOTOS

1. Area taped out
2. 1st coat of Belzona 3412 applied
3. Close up of application
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

