

BELZONA REPAIRS NEW HEAVY EQUIPMENT TIRE

ID: 889



PROBLEM

When the transport unloaded this brand new loader, the tire was damaged.

APPLICATION SITUATION

New front end loader being delivered to the local dealership.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The surface was prepared with a roughing brush and conditioned with Belzona® 2911 (QD Conditioner). The gouges in the rubber tire cover were rebuilt with Belzona® 2311.

BELZONA FACTS

The Belzona repair was completed quickly and its excellent adhesion and abrasion resistance will ensure it continues to perform in service.

INDUSTRY

General Industry

LOCATION

Equipment Dealership, South Central Kansas

APPLICATION DATE

June, 2007

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged portion of the tire
2. Roughened surface
3. Surface conditioned
4. Tire rebuilt with Belzona 2311

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

