


BELZONA SUPERWRAP 2 SYSTEM REPAIRS STORAGE TANK

ID: 8945



PROBLEM

A leak had developed in a storage tank due to corrosion.

APPLICATION SITUATION

No hot works were possible in the area due to the tank's location. A cold applied repair was required to repair this leak long term.

APPLICATION METHOD

The area was prepared with an MBX Bristle Blaster to SSPC SP11. A cold plate bond was then applied using Belzona 1111. This plate was then encapsulated with Belzona Superwrap 2

BELZONA FACTS

This repair was carried out in 1.5 days, allowing a fast return to service for the customer

INDUSTRY

Chemical & Petrochemical

LOCATION

Scotland

APPLICATION DATE

January 2023

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1981 (SuperWrap II)

SUBSTRATE

Carbon steel

PHOTOS

1. Leaking area
2. Belzona 1111 & Superwrap 2 applied
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

