


BELZONA SEALS THE GAP

ID: 8950



PROBLEM

ANTI-ACID TILE FLOOR FAILURE CAUSES DAMAGE AND LIFTING OF TILES, DUE TO THE RECURRING FAILURE IN THE JOINTS BETWEEN TILES.

APPLICATION SITUATION

THROUGH THE BELZONA SOLUTION SEAL THESE JOINTS AND PROTECT THE ENTIRE FLOOR THUS CONSIDERABLY INCREASING ITS USEFUL LIFE

APPLICATION METHOD

- 1- CLEAN THE AREA TO BE REPAIRED WITH BELZONA® 9411
- 2- SURFACE PREPERATION TO GIVE PROFILE
- 3- THE JOINTS ARE COVERED WITH TWO COATS OF BELZONA® 4311 UNTIL LEAVING THE FLOOR AT THE SAME LEVEL

BELZONA FACTS

BELZONA WAS ABLE TO OFFER A SOLUTION TO EXTEND THE LIFE OF THE TILED APPLICATION AND OREVENT INGRESS OF ACID THROUGH THE JOINTS.

INDUSTRY

Steel & Metal Processing

LOCATION

SPAIN

APPLICATION DATE

2017

PRODUCTS

Belzona 4311 (Magma CR1)

SUBSTRATE

Carbon steel

PHOTOS

1. INITIAL CONDITION
2. SURFACE PREPERATION
3. APPLICATION COMPLETED

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

