

BELZONA REPAIRS A CONVEYOR BELT FOR A ROBOTISED PHARMACEUTICAL DEPOT

ID: 8992



PROBLEM

The conveyor belt had ripped at the centre all along the belt (37m) except for 4m.

APPLICATION SITUATION

A conveyor belt (37m long) within a Pharmaceutical, which uses robots to pick medications prior to placing them on the conveyor belt.

APPLICATION METHOD

The conveyor belt was prepared by cutting out the damaged rip in order to ensure a clean application. A reinforcement sheet (Belzona 9341) was used in conjunction with a multipurpose liquid elastomer (Belzona 2221). The application was carried out in accordance with a modified version of Belzona System Leaflet SHM-01.

BELZONA FACTS

The approved Belzona Distributor, conducted this repair and was able to put the conveyor belt back in service in less than 24-hours.

INDUSTRY

General Industry

LOCATION

France

APPLICATION DATE

February 2023

PRODUCTS

Belzona 2221 (MP Fluid Elastomer)
Belzona 2921 (Elastomer GP Conditioner)
Accessories

SUBSTRATE

Rubber

PHOTOS

1. The conveyor belt being removed from service.
2. The conveyor belt mid-preparation.
3. The finished and repaired conveyor belt.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

