


BELZONA BEEFS UP ROCK BOX WEAR PAD

ID: 9030



PROBLEM

Weld overlay wasn't enough for the wear pads of this dredging rock box. This wear pad will see anything from mud, sand, oysters, rocks, dropped tools in the bottom of the ship channel, and many other hard objects picked up by the dredging pump.

APPLICATION SITUATION

The Belzona 1814 application was a faster method than weld overlay.

APPLICATION METHOD

Blasted to SSPC-SP10 - minimum 3-mil anchor

Primer coat of Belzona 1331 to increase adhesion of the Belzona 1814
1/4" of Belzona 1814 applied to all wear surfaces

BELZONA FACTS

Faster than weld overlay. Expert application. Close-To-Home service.

INDUSTRY

Marine

LOCATION

Houston, TX

APPLICATION DATE

PRODUCTS

Belzona 1331
Belzona 1814

SUBSTRATE

Other

PHOTOS

1. Wear Plate Before
2. Priming coat of Belzona 1331
3. Finished coat of Belzona 1814

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

