

BELZONA STOPPED PIPE LEAK

ID: 9040



PROBLEM

There were a cooling water pipe with leaking holes

APPLICATION SITUATION

It was a test application instead of welding.

Service pressure: 4 bar

Temperature: 10°C

APPLICATION METHOD

Surface preparation (MBX)

Cleaning (B9111)

Stop leaking (B9611)

Strengthen the pipe (SuperWrap II)

BELZONA FACTS

It was a test application instead of welding.

They would like to try the SuperWrap system on a high pressure gas pipe too.

INDUSTRY

Oil & Gas

LOCATION

Hungary

APPLICATION DATE

PRODUCTS

Belzona 1981 (SuperWrap II)

Belzona 9111 (Cleaner Degreaser)

Belzona 9611 (ES-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. Leaking hole
2. Surface preparation
3. Stopped leaking
4. Strengthen pipe section

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.