


BELZONA 1341 KEEPS SWIMMING POOL RUNNING SMOOTH YEAR ROUND

ID: 9041



PROBLEM

The client had a swimming pool water pump losing efficiency and was faced with either repair or replacement.

APPLICATION SITUATION

This pool water pump had erosion and corrosion issues from years of service in a wave pool. The client was given a choice between repair or replacement and looked to Belzona for a replacement solution.

APPLICATION METHOD

Pump was blasted to SP- 10
Rebuilt with 1121
2 coats of 1341

BELZONA FACTS

Faster and cheaper alternative to replacement due to this pump beginning to fail 1 month prior to the water park opening for summer.

INDUSTRY

Other

LOCATION

Galveston, TX

APPLICATION DATE

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 1341 (Supermetalgilde)

SUBSTRATE

Cast Iron

PHOTOS

1. Casing before coating showing wear from service
2. Pump plate before showing service wear
3. Freshly rebuilt and coated pump casing
4. Super smooth rebuilt and coating of Belzona 1341 to the pump plate

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

